



**2019 Prescott Hamfest at Embry- Riddle
Aeronautical University
May 31st & June 1st 2019**



We have cables and software to program:

Radio	Cable	Software	Radio	Cable	Software
<u>Alinco DJ-G7EG</u>	57B	CHIRP	<u>QYT KT7900D</u>	70	CHIRP
<u>AnyTone 5888UV</u>	29A	CHIRP	<u>QYT KT8900</u>	70	CHIRP
<u>BTECH UV-2501</u>	70	CHIRP	<u>QYT KT8900D</u>	70	CHIRP
<u>BTECH UV-2501+220</u>	70	CHIRP	<u>Radioddity QB25</u>	70	CHIRP
<u>BTECH UV-25X2</u>	70	CHIRP	<u>Retevis RT-5R</u>	K4Y	CHIRP
<u>BTECH UV-25X4</u>	70	CHIRP	<u>Retevis RT-5RV</u>	K4Y	CHIRP
<u>BTECH UV-5001</u>	70	CHIRP	<u>Retevis RT22</u>	K4Y	CHIRP
<u>BTECH UV-50X2</u>	70	CHIRP	<u>Rugged RH5R</u>	K4Y	CHIRP
<u>BTECH UV-5X3</u>	K4Y	CHIRP	<u>Rugged RH5R-V2</u>	K4Y	CHIRP
<u>Baofeng BF-888</u>	K4Y	CHIRP	<u>Rugged RH5X</u>	K4Y	CHIRP
<u>Baofeng BF-F8HP</u>	K4Y	CHIRP	<u>Sainsonic GT-890</u>	70	CHIRP
<u>Baofeng GT-3WP</u>	K4Y	CHIRP	<u>TYT TH-350</u>	K4Y	CHIRP
<u>Baofeng UV-5R</u>	K4Y	CHIRP	<u>TYT TH-UVF1</u>	K4Y	CHIRP
<u>Baofeng UV-5X</u>	K4Y	CHIRP	<u>TYT TH-UVF8D</u>	K4Y	CHIRP
<u>Baofeng UV-6</u>	K4Y	CHIRP	<u>WLN KD-C1</u>	K4Y	CHIRP
<u>Baofeng UV-6R</u>	K4Y	CHIRP	<u>Wouxun KG-UV6</u>	K4Y	CHIRP
<u>Baofeng UV-82</u>	K4Y	CHIRP	<u>Wouxun KG-UV8D</u>	K4Y	CHIRP
<u>Baofeng UV-82HP</u>	K4Y	CHIRP	<u>Wouxun KG-UV8D Plus</u>	K4Y	CHIRP
<u>Baofeng UV-82WP</u>	K4Y	CHIRP	<u>Wouxun KG-UV9D Plus</u>	K4Y	CHIRP
<u>Baofeng UV-B5</u>	K4Y	CHIRP	<u>Yaesu FT 1500</u>	29F	RTSYS
<u>Icom IC-7000</u>	RTS01	CHIRP	<u>Yaesu FT-1802M</u>	29F	CHIRP
<u>Icom IC-7100</u>	RTS01	CHIRP	<u>Yaesu FT-1D R</u>	68	CHIRP
<u>Icom IC-Q7A</u>	57A	CHIRP	<u>Yaesu FT-2800M</u>	29F	CHIRP
<u>Icom IC-T70</u>	29A	CHIRP	<u>Yaesu FT-2900R/1900R</u>	29F	CHIRP
<u>Icom IC-T90</u>	29A	RTSYS	<u>Yaesu FT-4XR</u>	55	CHIRP
<u>Icom IC-T7H</u>	29A	CHIRP	<u>Yaesu FT-50</u>	57A	CHIRP
<u>Icom IC-T8A</u>	29A	CHIRP	<u>Yaesu FT-60</u>	57A	CHIRP
<u>Icom IC-V82/U82</u>	29A	CHIRP	<u>Yaesu FT-65R</u>	55	CHIRP/RTSYS
<u>Icom IC-W32A VHF</u>	29A	CHIRP	<u>Yaesu FT-70D</u>	57B	CHIRP
<u>Icom IC-W32A UHF</u>	29A	CHIRP	<u>Yaesu FT-7100M VHF Band</u>	29B	CHIRP
<u>Icom IC-W32E VHF</u>	29A	CHIRP	<u>Yaesu FT-7100M UHF Band</u>	29B	CHIRP
<u>Icom IC-W32E UHF</u>	29A	CHIRP	<u>Yaesu FT-7800/7900</u>	29B	CHIRP
<u>Icom ID-880H</u>	29A	CHIRP	<u>Yaesu FT-8100 VHF</u>	29B	CHIRP
<u>Jetstream JT2705M</u>	70	CHIRP	<u>Yaesu FT-8100 UHF</u>	29B	CHIRP
<u>Juental JT-6188 Mini</u>	70	CHIRP	<u>Yaesu FT-817</u>	Yes	CHIRP
<u>Juental JT-6188 Plus</u>	70	CHIRP	<u>Yaesu FT-817ND (US)</u>	62C	CHIRP
<u>Kenwood TH-D7</u>	82	CHIRP	<u>Yaesu FT-818ND (US)</u>	62C	CHIRP
<u>Kenwood TH-D7G</u>	82	CHIRP	<u>Yaesu FT-857/897 (US)</u>	62C	CHIRP/RTSYS
<u>Kenwood TH-F6</u>	K4Y	CHIRP	<u>Yaesu FT-8800 Left</u>	29B	CHIRP
<u>Kenwood TH-F7</u>	K4Y	CHIRP	<u>Yaesu FT-8800 Right</u>	29B	CHIRP
<u>Kenwood TH-G71</u>	K4Y	CHIRP	<u>Yaesu FT-8900</u>	29B	CHIRP
<u>Kenwood TH-K2</u>	K4Y	CHIRP	<u>Yaesu FT2D R</u>	68	CHIRP
<u>Kenwood TM-271</u>	RPCK2	CHIRP	<u>Yaesu FT2D Rv2</u>	68	CHIRP
<u>Kenwood TM-281</u>	RPCK2	CHIRP	<u>Yaesu FTM-100</u>	SCU-20	CHIRP
<u>Kenwood TM-471</u>	RPCK2	CHIRP	<u>Yaesu FTM-3200D R</u>	29F	CHIRP
<u>Kenwood TM-D710</u>	K5G	CHIRP	<u>YAESU FTM400</u>	SCU-20	RTSYS
<u>Kenwood TM-D710G</u>	K5G	CHIRP	<u>Yaesu VX-2</u>	57A	CHIRP
<u>Kenwood TM-G707</u>	K4S	CHIRP	<u>Yaesu VX-3</u>	57A	CHIRP
<u>Kenwood TM-V7 VHF</u>	K4S	CHIRP	<u>Yaesu VX-5</u>	57A	CHIRP
<u>Kenwood TM-V7 UHF</u>	K4S	CHIRP	<u>Yaesu VX-6</u>	57B	CHIRP
<u>Kenwood TM-V71</u>	K5G	CHIRP	<u>Yaesu VX-7</u>	57B	CHIRP
<u>LUITON LT-316</u>	K4Y	CHIRP	<u>Yaesu VX-8DR</u>	59	CHIRP/RTSYS
<u>LUITON LT-588UV</u>	70	CHIRP	<u>Yaesu VX-8GE</u>	82	CHIRP
<u>Puxing PX-777</u>	K4Y	CHIRP	<u>Yaesu VX-8R</u>	82	CHIRP
<u>Puxing PX-888K</u>	K4Y	CHIRP	<u>YAESU VX-8G</u>	82	CHIRP/RTSYS
			<u>Zastone ZT-X6</u>	K4Y	CHIRP